

# Ideal Update Archive

- **October 8, 2001** - New software version 2.141 required for LT 8600T.
- **November 5, 2001** - New software version 1.332 required for LT 8100A and LT 8155T.
- **March 5, 2002** - New software version 2.15 required for LT 8600T.
- **May 22, 2002** - New software version 1.341 required for LT 8000, LT 8100, and LT 8155. New software version 2.161 required for LT 8600.
- **May 24, 2002** - LANTEK 6 and LANTEK 7 are now approved to test category 5e and category 6 permanent link and channels.
- **June 24, 2002** - New software version 1.101 required for LANTEK 6 and LANTEK 7.
- **October 14, 2002** - New software version 1.106 required for LANTEK 6 and LANTEK 7.
- **December 11, 2002** - New software version 1.109 required for LANTEK 6 and LANTEK 7.
- **December 12, 2002** - New software version 2.161 required for LT 8600T.